

MOSHE Advocacy Update

Top 10 Joint Commission Findings Non-Compliance Issues from 688 Hospitals (January 1, 2019 - June 30, 2019)

Greg Hrbacek, Advocacy Committee Chair, greg.hrbacek@bjc.org

Alexander F. Zivnuska, Advocacy Committee Co-Chair, alexz@codeconsultants.com

| Rank | Percentage of Non-Compliance | Standard | Program |
|------|------------------------------|-------------|--|
| 1 | 91% | LS.02.01.35 | Electrical wires lying on the Sprinkler system in the ceiling Corroded or painted sprinkler head |
| 2 | 80% | EC.02.05.01 | Air Pressure relation and air exchange in critical rooms such as Operating Rooms Installing Labels on Utility Lines |
| 3 | 78% | EC.02.06.01 | Interior spaces are safe and suitable for care Maintain ventilation temperature and humidity |
| 4 | 73% | LS.02.01.10 | Unprotected openings in fire rated walls and floor Fire door hardware and excessive gaps between door and framework |
| 5 | 71% | EC.02.05.05 | control airborne contaminants (such as biological agents, gases, fumes, dust) minimizes pathogenic biological agents in cooling towers, domestic hot/cold water systems |
| 6 | 70% | LS.02.01.30 | Hazardous storage area issues Corridor Doors Smoke barriers do not have unsealed penetrations |
| 7 | 68% | LA.02.01.20 | Corridor clutter Doors unlocked in the direction of egress |
| 8 | 65% | EC.02.05.09 | Medical Gas cylinder management Medical gas shut valves labeled and accessible |
| 9 | 65% | IC.02.02.01 | The Hospital manages risks related to Hazardous materials and waste |
| 10 | 64% | IC.02.01.01 | The Hospital Implements its infection prevention and control plan |

